A total of sixteen (16) WIB occurrences were reported for 2020 that, per ordinance, fall under the City of Amherst's coverage area.

Cooper Foster Park Sanitary District

- Eight (8) occurrences of WIB complaints were received.
 - One (1) occurrence was due to roots in the mainline sewer. A homeowner was having maintenance completed on his sanitary sewer lateral and pushed a root ball into the City's mainline, blocking the outlet of a downstream manhole.
 - One (1) occurrence was due to construction debris. A contractor working in a subdivision allowed construction debris to enter the City's sanitary sewer mainline. City crews restored services. The contractor was visited in the subdivision and advised on how to keep construction debris out of City sewers.
 - Four (4) occurrences were due to line deterioration. A manhole bench broke away, blocking the outlet of the manhole. This caused the mainline sanitary sewer to surcharge. City crews removed the obstruction and restored flow. This manhole has been added to the City's rehabilitation list.
 - Two (2) occurrences were due to a blockage in the mainline sewer. A contractor left a plug in the City's mainline sanitary sewer. This caused the line to surcharge and flood the basements of two homes. City crews removed the plug and restored flow.

Siphon Chamber Sanitary District

- Eight (8) occurrences of WIB complaints were received.
 - One (1) occurrence was due to a buildup of grease in the City's mainline sanitary sewer.
 City crews performed a CCTV inspection of the area. It was found that a sag in the mainline was allowing grease and debris to buildup causing the mainline blockage. This area will continue to be monitored.
 - Five (5) occurrences were due to roots in the mainline sewer. These line segments are currently on the City's root control list. We will continue to monitor these areas.
 - O Two (2) occurrences were due to a heavy rain.

All other sanitary sewer districts had zero (0) reported water in basement complaints that fall under the City of Amherst's coverage area.

The City of Amherst is continuing its efforts to identify cross connections, inflow and infiltration entering the sanitary sewer drainage basins. Utilizing flow metering, smoke testing, dye testing, video and visual inspection techniques to continue the reduction of I&I entering the system. In addition, the City's root control program, lift station maintenance activities, mainline cleaning activities, and line replacement program continue to keep sanitary sewer overflows to a minimum.

Joseph D. Jackson
City of Amherst Wastewater Collections Department
OEPA Class II WWC Operator
Core ID 1019966
jjackson@amherstohio.org
440-988-7625

Water In Basement Occurrences - Data Entry Spreadsheet

Permit Number 3PD00001*ND

Facility Name Amherst Water Pollution Control Center

Reporting Period

From 1/1/2020 To 12/31/2020

Sewershed	WIB Occurrences	Causes (choose all that apply)	Other Cause Description
Cooper Foster Park Sanitary District		8 Roots, Debris in Line, Line Deterioration	
Siphon Chamber Sanitary District		8 Grease, Line Deterioration, Roots, Extreme Weather	
Total Occurrences		16	

2020 WIB Occurences

Date of Work

Order Address	s/Location	<u>Issue</u>	Sanitary District	Comments
1/16/2020 117 Fall	l Lake	Debris in Line	Cooper Foster	Contractor left construction debris
3/13/2020 5544 Vi	rginia	Roots	Cooper Foster	Root ball from resident's lateral blocked outlet of manhole
3/30/2020 225 Cod	oper Foster	Line Deterioration	Cooper Foster	Manhole bench broke away blocking manhole outlet
3/30/2020 261 Cod	oper Foster	Line Deterioration	Cooper Foster	Manhole bench broke away blocking manhole outlet
4/1/2020 1118 M	leadowbrook	Line Deterioration	Cooper Foster	Manhole bench broke away blocking manhole outlet
4/6/2020 210 Cod	oper Foster	Line Deterioration	Cooper Foster	Manhole bench broke away blocking manhole outlet
10/21/2020 357 Peb	oble Creek	Debris in Line	Cooper Foster	Contractor left main line plug in sanitary sewer main
10/21/2020 353 Peb	oble Creek	Debris in Line	Cooper Foster	Contractor left main line plug in sanitary sewer main
3/16/2020 150 Orc	chard Hill	Line Deterioration. Grease	Siphon Chamber	Sag in pipe causes grease buildup
5/19/2020 453 Lon	ng	Roots	Siphon Chamber	Mainline root blockage
5/19/2020 454 Lon	ng	Roots	Siphon Chamber	Mainline root blockage
5/19/2020 457 Lon	ng	Roots	Siphon Chamber	Mainline root blockage
5/19/2020 459 Lon	ng	Roots	Siphon Chamber	Mainline root blockage
5/19/2020 460 Lon	ng	Roots	Siphon Chamber	Mainline root blockage
5/19/2020 179 Sipp	ple	Heavy Rain	Siphon Chamber	Heavy Rain
5/19/2020 603 N N	Лain	Heavy Rain	Siphon Chamber	Heavy Rain